



Switching clip

Application:

 To process earth connection measurement, opening of the circuit is allowed by disconnecting the copper plate with a wrench or a screwdriver.



	Ref -	Description	Fitting	Туре	Height	Width	Depth	Material
		Mounting						

UID: | TID:::05/10/2025| SID:::05/10/2025 | Issued:05/10/2025 10:26:21 am

Cedex rance 46 32 SICAME GROUP

Last Modification: 04/20/2025